

RELAIS in HB9 BrandMeister 13.05.2021 HB9BMC Röbi								
DMR ID	Name	Hardware	Firmware	TX	RX	CC	Status	Master
CH 228101	HB9GE1	Motorola XPR8400	R02.40.01	438.6750	431.0750	1	Slot 1 & 2 linked	2281
CH 228102	HB9GE2	Motorola SLR5500	R02.06.00.08	438.5500	430.9500	1	Slot 1 & 2 linked	2281
CH 228103	HB9AE-1	Motorola DR3000	R02.40.01	439.2000	431.6000	1	Slot 1 & 2 linked	2281
CH 228110	HB9IAP	Motorola MTR3000	R02.40.01	438.2500	430.6500	1	Slot 1 & 2 linked	2281
CH 228111	HB9VSD	Hytera RD625	A9.02.01.004	439.5375	431.9375	2	Slot 1 & 2 linked	2622
CH 228112	HB9RD	Hytera RD985	A7.00.09.005	438.6625	431.0625	1	Slot 1 & 2 linked	2281
CH 228123	HB9PE	Motorola DR3000	R02.10.00.13	439.6625	432.0625	1	Slot 1 & 2 linked	2622
CH 228125	HB9VD-1	Hytera RD985	A7.06.04.000	438.3375	430.7375	1	Slot 1 & 2 linked	2281
CH 228126	HB9PE	Motorola DR3000	R02.10.00.13	145.7875	145.1875	5	Slot 1 & 2 linked	2622
CH 228128	HB9AS-1	Motorola DR3000	R02.40.20	438.4250	430.8250	1	Slot 1 & 2 linked	2281
CH 228129	HB9PE	Hytera RD985	A9.02.01.004	439.4375	431.8375	2	Slot 1 & 2 linked	2622
CH 228131	HB9UCQ	MMDVM (Repeater)	20200615_Pi-Star_v4	438.3750	430.7750	1	Slot 1 & 2 linked	2281
CH 228132	HB9BR	Hytera RD985	A9.02.01.004	439.4000	431.8000	1	Slot 1 & 2 linked	2281
CH 228201	HB9FG-DMR	Hytera RD625	A7.06.04.000	438.4500	430.8500	1	Slot 1 & 2 linked	2281
CH 228202	HB9LC	MMDVM (Repeater)	20200615_Pi-Star_v4	438.5250	430.9250	1	Slot 1 & 2 linked	2281
CH 228301	HB9F1 BRRH	Motorola DR3000	R02.09.00.13	439.5000	431.9000	1	Slot 1 & 2 linked	2281
CH 228302	HB9F2 Schilthorn	Motorola DR3000	R02.09.00.03	438.2125	430.6125	1	Slot 1 & 2 linked	2281
CH 228305	HB9F3 Bern-City	Motorola DR3000	R02.06.00.07	438.5875	430.9875	1	Slot 1 & 2 linked	2281
CH 228312	HB9BO Niessen	Hytera RD985	A8.00.09.001	439.4125	431.8125	2	Slot 1 & 2 linked	2281
CH 228314	HB9Y5 Bagnes	Motorola DR3000	R02.40.20	439.4500	431.8500	3	Slot 1 & 2 linked	2281
CH 228316	HB9Y1 Oberwald	Motorola DR3000	R02.40.20	439.4875	431.8875	3	Slot 1 & 2 linked	2281
CH 228402	HB9BA	Motorola DR3000	R02.09.00.03	438.2250	430.6250	1	Slot 1 & 2 linked	2281
CH 228403	HB9FX	Hytera RD985	A7.00.09.005	438.4500	430.8500	2	Slot 1 & 2 linked	2281
CH 228404	HB9DM	Motorola SLR5500	R02.08.05.03	438.4375	430.8375	1	Slot 1 & 2 linked	2281
CH 228405	HB9CSR	MMDVM (Repeater)	20201031	438.5500	430.9500	1	Slot 1 & 2 linked	2281
CH 228409	HB9DM-2 L'bruck	Motorola DR3000	R02.08.05.03	438.3875	430.7875	1	Slot 1 & 2 linked	2281
CH 228411	HB9EAS-3 Rheinfe	Hytera RD625	A9.00.08.308.iM	438.4125	430.8125	1	Slot 1 & 2 linked	2281
CH 228412	HB9DM-4 TEST	Hytera RD625	A9.00.08.308.iM	438.3875	430.7875	2	Slot 1 & 2 linked	2281
CH 228414	HB9DM-3 Eptingen	Hytera RD985S	A9.00.08.308.iM	438.3250	430.7250	2	Slot 1 & 2 linked	2281
CH 228601	HB9DD-1 Generoso	Motorola DR3000	R02.06.00.07	438.4875	430.8875	1	Slot 1 & 2 linked	2222
CH 228602	HB9DD-2 Tamaro	Motorola DR3000	R02.30.02	438.4625	430.8625	1	Slot 1 & 2 linked	2622
CH 228603	HB9DD-3 Airolo	Motorola DR3000	R02.06.00.07	438.4875	430.8875	1	Slot 1 & 2 linked	2622
CH 228604	HB9DD-4 Biasca	Motorola DR3000	R02.30.12	438.4375	430.8375	1	Slot 1 & 2 linked	2621
CH 228605	HB9DD-5 Mendrisio	Motorola DR3000	R02.40.01	438.4375	430.8375	1	Slot 1 & 2 linked	2622
CH 228607	HB9DD-7 Mesocco	Motorola DR3000	R02.40.01	438.5125	430.9125	1	Slot 1 & 2 linked	2621
CH 228612	HB9CF Gotthard	Hytera RD625	A8.05.07.004	438.2250	430.6250	3	Slot 1 & 2 linked	2281
CH 228613	HB9LU Sonnenberg	Hytera RD625	A8.05.07.004	438.6250	431.0250	1	Slot 1 & 2 linked	2281
CH 228619	HB9DD-9 V.Maggia	Hytera RD625	A9.02.01.004	438.4375	430.8375	2	Slot 1 & 2 linked	2622
CH 228620	HB9ZG Rigi	Hytera RD985	A8.05.07.004	439.5375	431.9375	1	Slot 1 & 2 linked	2281
CH 228621	HB9GF	Hytera RD625	A7.06.04.000	438.2875	430.6875	1	Not linked	2082
CH 228693	HB9DS	MMDVM (Repeater)	20170501	439.5125	431.9125	1	Slot 1 & 2 linked	2082
CH 228701	HB9DD6 Poschiavo	Hytera RD625	A9.02.02.000	438.4875	430.8875	1	Slot 1 & 2 linked	2281
CH 228704	HB9OK6 St.Moritz	Hytera RD625	A9.00.10.100.iM	439.5625	431.9625	1	Slot 1 & 2 linked	2281
CH 228706	HB9DR-8	Hytera RD625	A8.05.07.004	439.5625	431.9625	2	Slot 1 & 2 linked	3021
CH 228708	HB9OK-5 Viano	Hytera RD625	A9.02.02.000	439.4500	431.8500	1	Slot 1 & 2 linked	2222
CH 228709	HB9OK-4	MMDVM (Repeater)	20181107_Pi-Star	145.6250	145.0250	1	Slot 1 & 2 linked	2222
CH 228807	HB9ZF	Motorola DR3000	R02.10.00.13	439.1000	431.5000	1	Slot 1 & 2 linked	2281
CH 228809	HB9AK-1 Hörnli	Hytera RD985	A8.01.03.001	438.6000	431.0000	1	Slot 1 & 2 linked	2281
CH 228811	HB9ZF-1	Motorola DR3000	R02.08.00.07	438.2625	430.6625	2	Slot 1 & 2 linked	2281
CH 228814	HB9TG1 Immenb	Hytera RD985	A8.05.07.001	439.4375	431.8375	1	Slot 1 & 2 linked	2281
CH 228815	HB9DC BM3	Hytera RD985S	A8.05.07.001	438.2125	430.6125	5	Slot 1 & 2 linked	2081
CH 228816	HB9TG2 Sulgen	Hytera RD625	A8.00.09.001	439.5750	431.9750	1	Slot 1 & 2 linked	2281
CH 228903	HB9DR-3	MMDVM (Repeater)	DMRGateway-20200421	438.2125	430.6125	1	Slot 1 & 2 linked	2281
CH 228904	HB9SG Hoher Kasten	RadioActivity KAIROS KA-450	1.6.9.0	438.3625	430.7625	1	Slot 1 & 2 linked	2281